ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
6

Ward Name
Thanisandra

Street ID
W0139, W0100, W0096, W0209, W0102, W0211, W0104, W

Street Name
NA, Kaveri Nagar Near Society Mahadevpura Post Whitefield Rd, Vinayaka Lyt 3rd Crs

Significant Landmark
Shirdi sai nagara and prashthi nagara

Segment No.
6/C-W0139/S053121

Total Length (m)
1668.10

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	39.31	77.639116	13.071607	77.639119	13.071252	Prashantinagar a 1st cross	cross road
2	444.39	77.639163	13.070654	77.638417	13.066707	Prashantinagar a 2nd cross	cross road
3	438.88	77.638872	13.070655	77.638100	13.066762	Prashantinagar a 3rd cross	cross road
4	217.06	77.638184	13.068749	77.637814	13.066821	Prashantinagar a 5th cross	cross road
5	213.65	77.637426	13.068885	77.637043	13.066990	Shiradi sai nagara 1st cross	cross road
6	210.38	77.637050	13.068942	77.636648	13.067082	Shiradi sai nagara 2nd cross	cross road
7	104.43	77.618424	13.062039	77.618461	13.061096	Shiradi sai nagara 3rd cross	cross road

Work Details

History of Road / Lane / Circles

Name of the Work
Package-2, includes 5 works of Rs.245.00 lakhs 1) Improvements to Roads and Drains at Mariyannapalya Church to Defence Layout and Dynasty Layout in Wa

Sanctioned Estimated Amount (Rs.)
24500000

Sanctioned Year
2017-18

Year
2017 - 2018

Type of Work
Road

Other Work Type

Tender
Tender

Work Details

Job No. / Work Code
006-18-000058,006-18-000060,006-18-000061,006-18-0

Work Order No.
BBMP/EE/BTP/WO/ 10/2018-19

Work Order Date
25/06/2018

Period of Extention

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಬ್ಯಾಟರಾಯನಪುರ ಉಪ ವಿಭಾಗ
ಬಿ.ಬಿ.ಎಂ.ಪಿ., ಬೆಂಗಳೂರು-24

Defect Liability Period From	Defect Liability Period To	Multiple road involved with the same Job No/ Work Code #
22/10/2018	22/10/2021	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
G. Venkatesh		0.00
Phone No.	**E-Mail ID**	
9845034278		

Field Inspection Details

Number of Trees	Any Other Information	Name
0		daramsingh c naik
Date of Inspection	**Remarks**	
23/10/2018		

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	R L Parameshwaraiah	25/10/2018	22/11/2018	As proposed
SE	Vasu K M	25/10/2018	22/11/2018	Completed
EE	Mohandas H.T	23/10/2018	22/11/2018	completed

Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0139, W0100, W0096, W0209,

AEE	Sridhar B.S	23/10/2018	22/11/2018	Verify
AE	Daramsingh C Naik	23/10/2018	22/11/2018	mobile verification is done
AE	Daramsingh C Naik	23/10/2018	22/11/2018	Forwarded



Zone: YELAHANKA **Ward No:** 6 **Ward Name:** Thanisandra **Street ID:** W0139, W0100, W0096, W0209,